The voltage rating highest setting highest set

Question 23 (3 marks)

Describe the process you should use to measure a resistor with a nominal value of 3
$1K\Omega$, using an analogue ohmmeter.
IKΩ, using an analogue ohmmeter. Check the office of the ohmotor of the ohmeter on resistance.
possible place on highest setting or
factor if resistor is in a circut disconnect
before in-serting podes into the positive and
regative terminals. When taking measurement
anoid paralax error and account for error
in the meansonment