

Start here.

a) Risk assessment.

- Proper foot protection.
- Use correct safety equipment e.g. safety goggles when drilling.
- Be steady when filing the edges.
- Caution metal can be hot after cutting or drilling it.
- Check cords of tools before using them in case they've been recently damaged.