

Start here.

Question 22

(a)

Risk: Metal piece flying off ~~the~~ drill

Solution: Clamp metal job with metal clamps securely.

Risk score: 2 out of 6

Risk: Metal ~~clamps~~ ^{snarf} flying into eyes

Solution: Wear protective goggles.

Risk score: 2 out of 6.

Risk: Drill piece snapping and lodging in job

Solution: Apply lubrication before hand

Sharpen drill bit.

Risk score: 1 out of 6.

Risk: Hazardous work area

Solution: Ensure the area is safe to work in, remove hazards.

Risk score: 1 out of 6

Risk: Malfunctioning equipment

Solution: Check tags ~~at~~ on machines and assess if

They are due for checkup and/or repair.

Risk score: 3 out of 6