

Start here.

Section IV Question (22)

Risks and Hazards	Hazard Rating, a being fine & being death
* cuts / stabbs	2
* eye damage	3
* hair being pulled out	1

control measures

* wear eye protection to avoid getting metal shards in the eyes.

* wear protective ~~steel~~ foot wear so you don't get injured if you drop metal on your foot

* keep hands clear from all cutting, sharpening and grinding tools to avoid cuts and stabbs

* wear a hair net to stop getting cut in tools such as drills.

* Remove all jewelry to avoid getting it cut in things.