

Start here.

b. The tools used should include: drill press, speed bore, hack saw and files.

Job diary entry

Made a couple of brackets today out of mild steel. Was the usual stock size 306 x 55 x 6 mm. Only needed a third of it for the bracket. Used a guillotine to cut it. Used the drill press to drill 3 holes. Then used a hack saw to join 2 of the holes together. Used a file to neaten it up afterwards. Also used a file to round one of the corners.